

Type	L #	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition	Errors
1	BRS	L1	159 Screw and jack and Socket and ("182"/\$.cc1s. or "248"/\$.cc1s. or "403"/\$.cc1s.)	USPAT ; EPO ; JPO ; DERWE NT	2005/03/1 5 15:08			
2	BRS	L2	10 11 and scaffold	USPAT ; EPO ; JPO ; DERWE NT	2005/03/1 5 14:57			
3	BRS	L3	2082 248/188.8.cc1s. or 248/188.4.cc1s. or 248/188.5.cc1s. or 248/354.1.cc1s. or 52/651.1.cc1s. or 52/126.3.cc1s.	USPAT ; EPO ; JPO ; DERWE NT	2005/03/1 5 15:02			
4	BRS	L4	0 13 and scaffold	USPAT ; EPO ; JPO ; DERWE NT	2005/03/1 5 15:02			
5	BRS	L5	48 13 and scaffold	USPAT ; EPO ; JPO ; DERWE NT	2005/03/1 5 15:07			

Type	L #	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Errors
6	BRS	L6	64 screw and jack and scaffold and ("182"/\$.cc1s. or "248"/\$.cc1s. or "403"/\$.cc1s.)	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:08			
7	BRS	L7	48 16 not (12 or 15)	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:14			
8	BRS	L8	1301 tube and cap and screw and jack	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:15			
9	BRS	L9	8 18 and scaffold	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:46			
10	BRS	L10	6131 drill and bit and tube	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:46			

Type	L #	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Errors
11	BRS	L11	2220 110 and (screw or thread)	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:47			
12	BRS	L12	22 111 and scaffold	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:47			
13	BRS	L13	20 "4026179"	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:52			
14	BRS	L14	12 "4026079"	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:55			
15	BRS	L15	15 "4122645"	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:57			

Type	L #	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Errors
16	BRS	L16	"4741505"	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:58			
17	BRS	L17	"2203114"	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 15:59			
18	BRS	L18	"3409266"	USPAT ; EPO; JPO; DERWE NT	2005/03/1 5 16:03			